

Inspection Photos

Operator: Kinder Morgan
Location/API #: 083-06383
Date: 4/3/2019



Photo 1. View of the project area from the northeastern project area facing center.



Photo 2. View of the northern project area from the northeastern corner facing westward. Revegetation is progressing within portions, and sparse in other portions of the interim reclamation areas.



Photo 3. View of Russian thistle debris within the interim reclamation area.



Photo 4. View of orange fencing debris within the eastern project area.



Photo 5. View of the southern project area from the southeastern corner facing westward.