

Final Reclamation and Stormwater Inspection

March 29, 2019

Operator: EXTRACTION OIL & GAS INC – 10459

Location ID: 320101

Inspection Document #: 674902727

Weld County, CO

NWNE Section 15 T1S R68W

Russell Beam
Reclamation Specialist, COGCC



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Photos
Location Name: EXTRACTION OIL & GAS/1S68W15
Location ID: 320101



Photo 1. Photo taken from the location, facing West. Operator has performed final reclamation activities with no equipment observed on location. Appears the location is currently under construction.



Photo 2. Photo taken from the location, facing North. See comments from Photo 1.