

Final Reclamation and Stormwater Inspection

March 29, 2019

Operator: EXTRACTION OIL & GAS INC – 10459

Location ID: 320222

Inspection Document #: 674902522

Weld County, CO

SESE Section 10 T1S R68W

Russell Beam
Reclamation Specialist, COGCC



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Photos

Location Name: EXTRACTION OIL & GAS/1S68W10

Location ID: 320222



Photo 1. Photo taken from the access road, facing West. Operator has performed final reclamation activities. However, the a section of the access road, cattle guard and gate remain on location.



Photo 2. Photo taken from the access road, facing East. See comments from Photo 1.

Inspection Photos

Location Name: EXTRACTION OIL & GAS/1S68W10

Location ID: 320222



Photo 3. Photo taken from the access road looking into the location, facing West. Operator has performed final reclamation activities.



Photo 4. Photo taken from the access road, facing East. See comments from Photo 3.

Inspection Photos

Location Name: EXTRACTION OIL & GAS/1S68W10

Location ID: 320222



Photo 5. Photo taken from the location, facing South. See comments from Photo 3.



Photo 6. Photo taken from the location, facing Northeast. See comments from Photo 3.