

Inspection Photos
Location Name: WEAVER RIDGE 24-6
Location ID: 05-103-10522
Inspection: 679703658



Photo 1. Location looking north.



Photo 2. Tank without capacity volume on label.

Inspection Photos

Location Name: WEAVER RIDGE 24-6

Location ID: 05-103-10522

Inspection: 679703658



Photo 3. Gas leaking at well head.

