

Inspection Photos
Location Name: WEAVER RIDGE 23-15
Location ID: 05-103-10581
Inspection: 679703665



Photo 1. Location looking northwest.



Photo 2. Tank without capacity volume.

Inspection Photos
Location Name: WEAVER RIDGE 23-15
Location ID: 05-103-10581
Inspection: 679703665



Photo 3. Container without label.



Photo 4. Container with illegible label.

Inspection Photos
Location Name: WEAVER RIDGE 23-15
Location ID: 05-103-10581
Inspection: 679703665

Leaking gas



Photo 5. Well head leaking gas & oily waste on ground.



Photo6. Pump jack dripping lubricant into open bucket.