

Inspection Photos
Location Name: AC #13-06
Location ID:08481



Photo 1 Sep/meter house



Photo 2 Production tank 30bbl

Inspection Photos
Location Name: AC #13-06
Location ID:08481



Photo 3 Loc pic




Photo 4 Unused equipment; seals, 15bbl tank. Unmarked, unused and not LOTO riser

Inspection Photos
Location Name: AC #13-06
Location ID:08481



Photo 5 Unused equipment; tubing, rods, horses head



Photo 6 Unmarked, unused and not LOTO riser