

Inspection Photos
Location Name: AC #14-15
Location ID: 308695



Photo 1 Sep/meter house. Unused, unmarked and not LOTO risers.



Photo 2 unmarked Guy line anchor

Inspection Photos
Location Name: AC #14-15
Location ID: 308695



Photo 3 Unused, unmarked and not LOTO risers.



Photo 4 Tank not painted appropriate color