

Inspection Photos
Location Name: AC #23-01
Location ID:308932



Colorado Oil and Gas Conservation Commission
37.07623, -104.9569, 2443.4m
Apr 11, 2019 12:20:47



Colorado Oil and Gas Conservation Commission
37.07623, -104.9567, 2443.8m
Apr 11, 2019 12:21:41

Photo 1 Sep/meter house, Liquid ring sound walls

Photo2 WH and HYD skid sound walls

Inspection Photos
Location Name: AC #23-01
Location ID:308932



**Photo 3 25bbl buried production tank. Wild life protection
2" 90's no bull plugs.**

Photo 4 improperly marked guy line anchor

Inspection Photos
Location Name: AC #23-01
Location ID:308932



Photo 5 Unused roof

