

Inspection Photos
Location Name: Golden Eagle Mine #GE69-93
Location ID: 307405



Photo 1 Sep/meter house



Photo 2 all production equipment removed. Unmarked, unused and LOTO risers

Inspection Photos
Location Name: Golden Eagle Mine #GE69-93
Location ID: 307405



Photo 3 stained soil under what appears to be a drip.



Photo 4 Stained soil and unused, unmarked and not LOTO risers