

Laramie Energy LLC
Api # 05-077-08773
Inspection # 675002158



Photo of location at entrance

Laramie Energy LLC
Api # 05-077-08773
Inspection # 675002158



Photo of tank battery



Photo of wellhead

Laramie Energy LLC
Api # 05-077-08773
Inspection # 675002158



Battery sign posted at entrance.



Hole in tank containment liner