

Inspection Photos
Location Name: Great Western Pad 8
Location ID: 333033



Photo 1 – Separators, trash to be removed



Photo 2 – Unused hose to be removed

Inspection Photos
Location Name: Great Western Pad 8
Location ID: 333033



Photo 3 – Stained soil around load line bucket




Photo 4 – Stained soil at the loadline

Inspection Photos
Location Name: Great Western Pad 8
Location ID: 333033



Photo 5 – Debris from near by trees



Photo 6 – Wellhead 27-14, Shut-In. Unused equipment

Inspection Photos
Location Name: Great Western Pad 8
Location ID: 333033



Photo 7 – Wellhead 27-24, Shut-In. Unused equipment



Photo 8 – Wellhead 27-53, TA. Unused equipment

Inspection Photos
Location Name: Great Western Pad 8
Location ID: 333033



Photo 9 – Wellhead 27-13, TA. Unused equipment



Photo 10 – Tank Battery Sign