

**Inspection Photos**  
**Location Name: Great Western Pad 7**  
**Location ID: 333027**



**Photo 1 – Wellhead 27-41**



**Photo 2 – Casing Collar leak, stained soil**



**Inspection Photos**  
**Location Name: Great Western Pad 7**  
**Location ID: 333027**



**Photo 3 – Wellhead 27-32**



**Photo 4 – Wellhead 27-31**



**Inspection Photos**  
**Location Name: Great Western Pad 7**  
**Location ID: 333027**



**Photo 5 – Wellhead 27-51**



**Photo 6 – Wellhead 27-51 Casing Collar leaking and stained soil**



**Inspection Photos**  
**Location Name: Great Western Pad 7**  
**Location ID: 333027**



**Photo 7 – Pad 7 Tank Battery**



**Photo 8 – Stained soil at loadline bucket**

**Inspection Photos**  
**Location Name: Great Western Pad 7**  
**Location ID: 333027**



**Photo 9 – Stained soil at loadline bucket**



**Photo 10 – Stained soil at loadline bucket**