

# Inspection Photos

API: 05-071-07989

Operator: TIMBER CREEK OPERATING LLC

Inspection Date: 4/12/2019

## Inspection Photos



**Photo 1.** Facing toward the location.

## Inspection Photos



**Photo 2.** Water level at the pit is nearing 2ft freeboard.



## Inspection Photos



**Photo 3.** There are numerous Scotch thistle plants emerging at the east side of the location.