

Inspection Photos
Location Name: NHF-65N63W /9NWSW
Location #: 331573



Colorado Oil & Gas Conservation Commission
40.41229, -104.44872, 1426.0m, 303°
2019/04/12 01:17:39 PM

Photo #1
NHF 13-9 (05-123-20921) Wellsite
Temporarily Abandoned | TA
Stained soil at wellhead perimeter



Colorado Oil & Gas Conservation Commission
40.40845, -104.44735, 1413.0m, 34°
2019/04/12 02:04:57 PM

Photo #2
NHF 13-9, 24-9 Battery
Shut-down

Inspection Photos
Location Name: NHF-65N63W /9NWSW
Location #: 331573



Photo #3
NHF 13-9, 24-9 Battery
Unused Equipment
Gas meter run, riser

