

Inspection Photos
Location Name: AC# 29-04
Location ID: 309237



**Photo 1 Sep/Meter house, 30bbl produced water tank and
Liquid ring sound walls.**



Photo 2 WH and HYD motor skid

Inspection Photos
Location Name: AC# 29-04
Location ID: 309237



Photo 3 Stained soil around HYD motor skid. Trash (1x4 boards)




Photo 4 Stained soil around liquid ring skid.

Inspection Photos
Location Name: AC# 29-04
Location ID: 309237



Photo 5 Stained soil around liquid ring skid.



Photo 6 Produced water pit.

Inspection Photos
Location Name: AC# 29-04
Location ID: 309237



Photo 7 Produced water pit.