

Inspection Photos
Location Name: HR# 29-13
Location ID: 309172



Photo 1 sep/meter house.



Photo 2 WH and HYD motor skid.

Inspection Photos
Location Name: HR# 29-13
Location ID: 309172



Photo 3 stained soil around WH



Photo 4 Stained soil around HYD motor skid

Inspection Photos
Location Name: HR# 29-13
Location ID: 309172



Photo 5 Produced water pit.