

Inspection Photos
Location Name: HR#32-01V and HR#32-01
Location ID: 312079



Photo 1 Dual sep/meter house for HR#32-01V and HR#32-01



Photo 2 HR#32-01V WH and PU.

Inspection Photos
Location Name: HR#32-01V and HR#32-01
Location ID: 312079



Photo 3 HR#32-01 WH and PU



Photo 4 Produced water pit #1

Inspection Photos
Location Name: HR#32-01V and HR#32-01
Location ID: 312079



Photo 5 Produced water pit #2