

# Inspection Photos

Operator: Kinder Morgan  
Location/API #: 083-06189  
Date: 4/3/2019



Photo 1. View of the project area from the northwestern project area facing center.



Photo 2. View of the western project area from the northwestern corner facing southward.



Photo 3. View of the northern project area from the northeastern corner facing westward.