

# Inspection Photos

Operator: Kinder Morgan  
Location/API #: 083-06706  
Date: 4/3/2019



Photo 1. View of the project area from the southwestern project area facing center.



Photo 2. View of the western project area from the southwestern corner facing northward. Revegetation within the interim reclamation area remains sparse, although progressing within portions of the interim reclamation area.



Photo 3. View of the southern project area from the southwestern corner facing eastward.