

Final Reclamation and Stormwater Inspection

March 29, 2019

Operator: PDC ENERGY INC – 69175

Location ID: 320312

Inspection Document #: 674902729

Weld County, CO

SENW Section 15 T1S R68W

Russell Beam
Reclamation Specialist, COGCC



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Photos
Location Name: PDC ENERGY INC /1S68W15
Location ID: 320312



Photo 1. Photo taken from the access road looking the location, facing East. Appears Operator has performed final reclamation activities with the evidence of drill rows and perennial grass revegetation.



Photo 2. Photo taken from the access road, facing West. See comments from Photo 1.

Inspection Photos
Location Name: PDC ENERGY INC /1S68W15
Location ID: 320312



Photo 3. Photo taken from the location. See comments from Photo 1.



Photo 4. Photo taken from the location, facing East. Appears sections of the reclamation is not at percent cover and has non-uniform establishment of vegetation cover.

Inspection Photos
Location Name: PDC ENERGY INC /1S68W15
Location ID: 320312



Photo 5. Photo taken from the location. See comments from Photo 4.



Photo 6. Photo taken from the location. Diffuse Knapweed (*Acosta diffusa*), A Colorado list B noxious weed, was observed on location.

Inspection Photos
Location Name: PDC ENERGY INC /1S68W15
Location ID: 320312




Photo 7. Photo taken from the location. Appears See comments from Photo 6.



Photo 8. Photo taken from the location, facing West. See comments from Photo 4.