

Inspection Photos

Location Name: 70 RANCH LAURA-65N63W /20SWSE

Location #: 332433



Colorado Oil & Gas Conservation Commission
40.3808, -104.45772, 1365.0m, 48°
2019/04/15 01:34:00 PM

Photo #1

70 Ranch Laura 34-20 (05-123-22293) Wellsite

Weeds need cleared
Trash needs removed



Colorado Oil & Gas Conservation Commission
40.38444, -104.46608, 1380.0m, 54°
2019/04/15 02:14:49 PM

Photo #2

70 Ranch-Laura 13, 14, 24, 34, CSW-20 Battery

