

**FORM
INSP**

Rev
X/15

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

04/12/2019

Submitted Date:

04/12/2019

Document Number:

692601654

FIELD INSPECTION FORM

Loc ID 303501 Inspector Name: Welsh, Brian On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

OGCC Operator Number: 10536
Name of Operator: SMITH ENERGY LLC
Address: 1540 MAIN ST SUITE 218 #334
City: WINDSOR State: CO Zip: 80550

Findings:

10 Number of Comments
0 Number of Corrective Actions
 Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
Smith, Glenn	(970) 330-7034	gsmithten@what-wire.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
253202	WELL	PR	12/01/2017	GW	125-07079	MCCAULEY 1-18	PR

General Comment:

[Routine Inspection](#)

Location

Lease Road:			
Type	Access		
comment:	Trail through pasture		
Corrective Action:		Date:	

Overall Good:

Signs/Marker:			
Type	WELLHEAD		
Comment:	Lease sign by wellhead		
Corrective Action:		Date:	
Type	TANK LABELS/PLACARDS		
Comment:	Metal sign by fence		
Corrective Action:		Date:	
Type	OTHER		
Comment:	Lease sign by fence		
Corrective Action:		Date:	

Emergency Contact Number:			
Comment:	<input style="width: 95%;" type="text"/>		
Corrective Action:	<input style="width: 95%;" type="text"/>	Date:	<input style="width: 80%;" type="text"/>

Overall Good:

Spills:			
Type	Area	Volume	

In Containment: No

Comment:

Multiple Spills and Releases?

Fencing/:			
Type	LOCATION		
Comment:	Wire fence around entire location		
Corrective Action:		Date:	

Equipment:					corrective date
Type: Vertical Separator	# 1				
Comment:	Vertical gas separator in metal shed for McCauley 1-18				
Corrective Action:		Date:			
Type: Gas Meter Run	# 2				
Comment:	Shared meter run for McCauley 1-18 & 2-18				
Corrective Action:		Date:			

Tanks and Berms:					
Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	<50 BBLS	OTHER		39.883120,-102.799500

Comment:	Culvert 95% buried between meter sheds with metal screen. Empty and dry at time of inspection			
Corrective Action:				Date:
Paint				
Condition				
Other (Content)				
Other (Capacity)	25bbbs			
Other (Type)				
Berms				
Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Comment:				
Corrective Action:				Date:
Venting:				
Yes/No	NO			
Comment:				
Corrective Action:				Date:
Flaring:				
Type				
Comment:				
Corrective Action:				Date:

Inspected Facilities

Facility ID: 253202 Type: WELL API Number: 125-07079 Status: PR Insp. Status: PR

Producing Well

Comment: [Producing. Casing production. Central meter run for \(McCauley 1-18 & 2-18\)](#)

Corrective Action:

Date:

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Compaction	Pass	Compaction	Pass			

Comment:

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT