

SG 43-28
Api. # 05-045-10959
Inspection # 689703040



SG 43-28
Api. # 05-045-10959
Inspection # 689703040



Stained ground around chemical container.

SG 43-28
Api. # 05-045-10959
Inspection # 689703040



Stained ground around wells

SG 43-28
Api. # 05-045-10959
Inspection # 689703040



Storm water around SG 43-28



Storm water around SG 43-28

SG 43-28
Api. # 05-045-10959
Inspection # 689703040



Sediment build up in ditch



Waddle damaged in front of separators

SG 43-28
Api. # 05-045-10959
Inspection # 689703040



Erosion and sediment movement at tank battery