

Inspection Photos

API: 05-071-06300

Operator: TIMBER CREEK OPERATING LLC

Inspection Date: 4/12/2019

Inspection Photos



Photo 1. There is a dripping water leak from the wellhead.

Inspection Photos



Photo 2. Facing toward the location.