

Inspection Photos
Location Name: FEDERAL 16-22
Location ID: 05-103-08999
Inspection: 679703748



Photo 1. Location looking northeast.



Photo 2. Tubing casing pressure.



Inspection Photos
Location Name: FEDERAL 16-22
Location ID: 05-103-08999
Inspection: 679703748



Photo 3. Casing pressure gage on 4-16-2019.



Photo 4. Casing pressure gage on 12-26-2018,