

Inspection Photos  
Location Name: Sawdey #22-30  
Location ID: 323043



Photo 1 WH



Photo 2 2" piping from WH to flow line disconnected and laying on ground. Unused equipment and unmarked, unused and not LOTO riser.