

# Final Reclamation and Stormwater Inspection

March 29, 2019

Operator: EXTRACTION OIL & GAS INC – 10459

Location ID: 320263

Inspection Document #: 674902772

Weld County, CO

NESE Section 15 T1S R68W

Russell Beam  
Reclamation Specialist, COGCC



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

Inspection Photos  
Location Name: EXTRACTION OIL & GAS/1S64W15  
Location ID: 320263



**Photo 1.** Photo taken from the access road off Washington St., facing West. Appears a concrete pad and gravel has been installed at the entrance to the access road.



**Photo 2.** Photo taken from the access road , facing East. See comments from Photo 1.

## Inspection Photos

Location Name: EXTRACTION OIL & GAS/1S64W15

Location ID: 320263



**Photo 3.** Photo taken from the access road, facing West. Appears part of the access road still remains. Photo also depicts a raptor nest observed on location with two Red-tailed hawks observed.



**Photo 4.** Photo taken south of the access road, facing East. Photo depicts the recently installed drainage way.

## Inspection Photos

Location Name: EXTRACTION OIL & GAS/1S64W15

Location ID: 320263



**Photo 5.** Photo taken from the location, facing West. Photo depicts a recently installed gravel trail at the location.



**Photo 6.** Photo taken from the location, facing Southeast. Appears reclamation activities have recently been performed with the evidence of drill rows and straw crimped mulch.

Inspection Photos  
Location Name: EXTRACTION OIL & GAS/1S64W15  
Location ID: 320263



**Photo 5.** Photo taken from the location, facing Southwest. See comments from Photo 4.



**Photo 6.** Photo taken from the location, facing East. See comments from Photo 4.