

Laramie Energy LLC
Api # 05-077-10427
Inspection # 675002175



Photo of location

Laramie Energy LLC
Api # 05-077-10427
Inspection # 675002175



Photo of tank battery



Photo of wellhead

Laramie Energy LLC
Api # 05-077-10427
Inspection # 675002175



Erosion through berm,

Close up of erosion through berm

Laramie Energy LLC
Api # 05-077-10427
Inspection # 675002175



Berm not compacted or stabilized



BMP needs maintenances Water running under waddle

Laramie Energy LLC
Api # 05-077-10427
Inspection # 675002175



Slope not stabilized



Slope not stabilized

Laramie Energy LLC
Api # 05-077-10427
Inspection # 675002175



Stored equipment on location



Stored equipment on location

Laramie Energy LLC
Api # 05-077-10427
Inspection # 675002175



Trash inside tank containment