

Laramie Energy LLC
Api # 05-077-10104
Inspection # 675002179



Photo of location from entrance

Laramie Energy LLC
Api # 05-077-10104
Inspection # 675002179



Photo of tank battery



Photo of wellhead

Laramie Energy LLC
Api # 05-077-10104
Inspection # 675002179



Unused equipment stored on location



Unused equipment stored on location

Laramie Energy LLC
Api # 05-077-10104
Inspection # 675002179



Trash on location



Stained soil around wellhead

Laramie Energy LLC
Api # 05-077-10104
Inspection # 675002179



Containment full.



Trash or unused equipment left on location

Laramie Energy LLC
Api # 05-077-10104
Inspection # 675002179



BMP in need of repair or maintenance



BMP in need of repair or maintenance

Laramie Energy LLC
Api # 05-077-10104
Inspection # 675002179



BMP in need of repair or maintenance



Loss of compaction