

Laramie Energy LLC
Api # 05-077-10371
Inspection # 675002181



Photo of location from entrance

Laramie Energy LLC
Api # 05-077-10371
Inspection # 675002181



Photo of tank battery



Photo of wellhead

Laramie Energy LLC
Api # 05-077-10371
Inspection # 675002181



Berm has evidence of erosion and needs repaired



Silt fence BMP needs maintenance

Laramie Energy LLC
Api # 05-077-10371
Inspection # 675002181



Heavy erosion of hill side do to no stabilization



No Berm around soil pile

Laramie Energy LLC
Api # 05-077-10371
Inspection # 675002181



No Berm around soil pile



Sediment moving over the top of wattle. In need of maintenance.