

# *Inspection Photos*

*API#103-06235*

*Operator: Chevron*

*Inspection Number: 692400884*

*Inspection Date: 3/29/19*





Photo#1:  
Overview of Location to West.

March 29, 2019



Photo#2:  
Overview of Location to South.

March 29, 2019



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources

Inspection Photos: Chevron PA Calco Hayes 16 API#103-06235



Photo#3:  
View of valve at backside of tank.



Photo#4:  
Pit area on Southwest corner of site.

March 29, 2019



Photo#5:  
Shed at South edge of site.

March 29, 2019



Photo#6:  
View to East over West side of site.