

Inspection Photos

4/16/2019

Operator: NOBLE ENERGY INC # 100322

Location ID: 432189

Inspection Doc. Number: 682504745

Weld County, CO

Aaron Trujillo
NE Reclamation Specialist
COGCC



Photo 1: Photo taken from the northwest interim area of the location, facing south. Photo shows striations in the soil indicating additional seeding activities have been conducted via not-till seed drill.



Photo 2: Photo taken from the northwest interim area of the location, facing south. Previous inspection documented gravel/base has not been removed from the interim areas and hindering reclamation. Inspection required operator to remove gravel/base. Photo shows gravel has not been removed from the interim area. Operator appears to have attempted to seed into the gravel rather than remove and reclaim.

Inspection Photos
Operator: NOBLE ENERGY INC # 100322
Location ID: 432189



Photo 3: Photo taken from the west interim area of the location, facing south. Photo slopes appear to have been seeded and mulched.



Photo 4: Photo taken from the south end of the location, facing west. Photo slopes appear to have been seeded and mulched.