

Inspection Photos

4/16/2019

Operator: NOBLE ENERGY INC # 100322

Location ID: 433177

Inspection Doc. Number: 682504747

Weld County, CO

Aaron Trujillo
NE Reclamation Specialist
COGCC



Photo 1: Photo taken from the south end of the location, facing east. Photo shows additional reclamation has been conducted.



Photo 2: Photo taken from the south end of the location, facing south. Photo shows additional reclamation has been conducted.



Photo 3: Photo taken from the north end of the location, facing northwest. Photo shows additional reclamation has been conducted on the slopes of the north end of the location.



Photo 4: Photo taken from the northwest end of the pad, facing south. Photo shows operator appears to have seeded/mulched slopes on the east.