

Inspection Photos

4/16/2019

Operator: NOBLE ENERGY INC # 100322

Location ID: 433090

Inspection Doc. Number: 682504751

Weld County, CO

Aaron Trujillo
NE Reclamation Specialist
COGCC



Photo 1: Photo taken from the south end of the location, facing east. Photo shows vegetation over the reclamation area.



Photo 2: Photo taken from the south end of the location, facing northeast. Photo shows vegetation over the reclamation area.



Photo 3: Photo taken from the south end of the location, facing north. Photo shows vegetation over the reclamation area.