

Inspection Photos

4/16/2019

Operator: NOBLE ENERGY INC # 100322

Location ID: 440380

Inspection Doc. Number: 682504755

Weld County, CO

Aaron Trujillo
NE Reclamation Specialist
COGCC

Inspection Photos
Operator: NOBLE ENERGY INC # 100322
Location ID: 440380



Photo 1: Photo taken from the location. Photo shows the two PR wells.



Photo 2: Photo taken from the south end of the location, facing east. Photo shows vegetation over the reclamation area. Interim areas are either predominantly undersirable weedy plant species such as Kochia, Salsola sp, or bare and exposed soil.



Photo 3: Photo taken from the south end of the location, facing northeast. Photo shows vegetation over the reclamation area. Interim areas are either predominantly undersirable weedy plant species such as Kochia, Salsola sp, or bare and exposed soil.



Photo 4: Photo taken from the south end of the location, facing north. Photo shows vegetation over the reclamation area. Interim areas are either predominantly undersirable weedy plant species such as Kochia, Salsola sp, or bare and exposed soil.



Photo 5 Photo taken from the interim areas. Photo shows plant germination observed on interim areas is undesirable weedy plant species such as Kochia and Salsola sp. Inspector was unable to observe desirable perennial vegetative germination.