

Inspection Photos

4/16/2019

Operator: NOBLE ENERGY INC # 100322

Location ID: 440372

Inspection Doc. Number: 682504763

Weld County, CO

Aaron Trujillo
NE Reclamation Specialist
COGCC



Photo 1: Photo taken from the location. Photo shows the three PR wells.



Photo 2: Photo taken from the northwest end of the location, facing south. Photo shows vegetation over the reclamation area. Interim areas are either predominantly undersirable weedy plant species such as Kochia, Salsola sp, or bare and exposed soil.



Photo 3: Photo taken from the northwest end of the location, facing southeast. Photo shows vegetation over the reclamation area. Interim areas are either predominantly undersirable weedy plant species such as Kochia, Salsola sp, or bare and exposed soil.



Photo 4: Photo taken from the northwest end of the location, facing east. Photo shows vegetation over the reclamation area. Interim areas are either predominantly undersirable weedy plant species such as Kochia, Salsola sp, or bare and exposed soil.



Photo 5 Photo taken from the interim areas. Photo shows plant germination observed on interim areas is undesirable weedy plant species such as Kochia and Salsola sp. Some desirable perennial germination was evident.