

# Inspection Photos

4/16/2019

Operator: NOBLE ENERGY INC # 100322

Location ID: 423807

Inspection Doc. Number: 682504765

Weld County, CO

Aaron Trujillo  
NE Reclamation Specialist  
COGCC



**Photo 1:** Photo taken from the west end of the location, facing south. Photo shows vegetation over the interim area.



**Photo 2:** Photo taken from the west end of the location, facing southeast. Photo shows vegetation over the interim area.



**Photo 3:** Photo taken from the west end of the location, facing northeast. Photo shows vegetation over the interim area.



**Photo 4:** Photo taken from the west end of the location, facing north. Photo shows vegetation over the interim area.



**Photo 5** Photo taken from the interim area. Photo shows vegetation appears to be progressing towards reclamation standards.