

**Inspection Photos**  
**Location Name: McElmo Dome Unit 9-38-18 HWD-1**  
**API: 05-083-06240**



**HWD-1 location photo.**



**Fiberglass shack housing injection well.**

## Inspection Photos

Location Name: McElmo Dome Unit 9-38-18 HWD-1

API: 05-083-06240



**Tank battery Facility ID #450887.**



**RW Trucking water hauler on site during this inspection.**



**Inspection Photos**  
**Location Name: McElmo Dome Unit 9-38-18 HWD-1**  
**API: 05-083-06240**



**Water hauler on site during this inspection. Spill prevention tub under valve on truck.**



**Point source of Spill/Release Point ID #463712.**