

Inspection Photos
Location Name: KUX 21-33
API #: 05-071-06544
Insp. Doc. # 695100532



PHOTO 1: LOCATION

PHOTO 2: METER HOUSE/WELL SIGN

Inspection Photos
Location Name: KUX 21-33
API #: 05-071-06544
Insp. Doc. # 695100532



PHOTO 3: IMPACTED SOIL ON NORTHWEST SIDE OF PUMPJACK SKID NEAR PRIME MOVER

PHOTO 4: IMPACTED SOIL ON NORTH SIDE OF PUMPJACK SKID NEAR PRIME MOVER