

Inspection Photos

Location Name: 70 RANCH LAURA-65N63W /20SESW

Location #: 332694



Photo #1

70 Ranch Laura 24-20 (05-123-22288) Wellsite

Stained soil at wellhead

from prior FIR



Photo #2

70 Ranch Laura 24-20 Wellsite

Stained soil appears remediated



Inspection Photos

Location Name: 70 RANCH LAURA-65N63W /20SESW

Location #: 332694



Photo #3

70 Ranch Laura 14-20 (05-123-22292) Wellsite

from prior FIR



Photo #4

70 Ranch Laura CSW-20 (05-123-24031) Wellsite

from prior FIR



Inspection Photos

Location Name: 70 RANCH LAURA-65N63W /20SESW

Location #: 332694



Photo #5

70 Ranch-Laura 13, 14, 24, 34, CSW-20 Battery

from prior FIR

