

Inspection Photos

Location Name: 70 RANCH LAURA-65N63W /20SWSE

Location #: 332433



Photo #1

70 Ranch Laura 34-20 (05-123-22293) Wellsite

Weeds need cleared

Trash needs removed

from prior FIR



Photo #2

70 Ranch Laura 34-20 Wellsite

Weeds NOW cleared

Trash NOW removed



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos

Location Name: 70 RANCH LAURA-65N63W /20SWSE

Location #: 332433



Photo #3

70 Ranch-Laura 13, 14, 24, 34, CSW-20 Battery

from prior FIR



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources