

Maralex Resources Inc.
Api # 05-077-08410
Inspection # 675002190



Photo of location from entrance

Maralex Resources Inc.
Api # 05-077-08410
Inspection # 675002190



Photo of location from entrance

Maralex Resources Inc.
Api # 05-077-08410
Inspection # 675002190



Wellhead

Maralex Resources Inc.
Api # 05-077-08410
Inspection # 675002190



Risers on location



Risers on location

**Maralex Resources Inc.
Api # 05-077-08410
Inspection # 675002190**



Ditch runs into sediment trap need maintenance



Drainage ditch on location