

Inspection Photos

Location Name: DRAGON TRAIL UNIT 1075

Location ID: 05-103-09434

Inspection: 679703770



Photo 1. Location looking west.



Photo 2. Tank liner is torn.



Inspection Photos

Location Name: DRAGON TRAIL UNIT 1075

Location ID: 05-103-09434

Inspection: 679703770



Photo 3. Liner debris in brush blown off location.



Photo 4. Storm water run on into location.

Inspection Photos

Location Name: DRAGON TRAIL UNIT 1075

Location ID: 05-103-09434

Inspection: 679703770



Photo 5. Tracking off location.



Photo 6. "911" missing on battery sign.



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources