

Inspection Photos

Location Name: DRAGON TRAIL UNIT 1150

Location ID: 05-103-09602

Inspection: 679703772



Photo 1. Location looking southeast.



Photo 2. Tank liner is torn.

Inspection Photos

Location Name: DRAGON TRAIL UNIT 1150

Location ID: 05-103-09602

Inspection: 679703772



Photo 3. Run off from the northwest side of the location through a breached berm.



Photo 4. Soil scour on the southeast hillside of location.



Inspection Photos

Location Name: DRAGON TRAIL UNIT 1150

Location ID: 05-103-09602

Inspection: 679703772



Photo 5. Trash that ran off location through a breached berm.



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources