

**Inspection Photos**  
**Operator: BP America**  
**Location/API #: 067-09270**  
**Date: 4-12-2019**



Photo 1. View of the project area from the southwestern corner facing center.



Photo 2. View of the southern project area from the southwestern corner facing eastward.



Photo 3. View of grazed vegetation in early season condition within the interim reclamation area.