

Inspection Photos
Location Name: Nelson E 1 Battery
Location ID: 336337



Photo 1 Ray Nelson #24-32,#14-32,#13-32 Well heads



Photo 2 Meter house, ECD's and Separators.

Inspection Photos
Location Name: Nelson E 1 Battery
Location ID: 336337



Photo 3 TNK BTRY



Photo 4 Unused equipment (separators 2) Unmarked unused and not LOTO risers

Inspection Photos
Location Name: Nelson E 1 Battery
Location ID: 336337



Photo 5 Unused equipment (separators 2) Unmarked unused and not LOTO risers



Photo 6 Ray Nelson #14-32 Stained soil around well head. Mechanical issue appears well head is leaking.

Inspection Photos
Location Name: Nelson E 1 Battery
Location ID: 336337



**Photo 7 Ray Nelson #14-32 Stained soil around well head.
Mechanical issue appears well head is leaking.**