

Inspection Photos

Location Name: 70 RANCHUSX BB-65N63W /35NENW

Location #: 310232



Photo #1

70 RanchUSX BB 35-03 (05-123-26107) Wellsite

Plugged & Abandoned | PA

≈ 50 yds.



Photo #2

70 RanchUSX BB 35-03 Battery site

Abandoned

Unused Equipment

Gas meter run, riser



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos

Location Name: 70 RANCHUSX BB-65N63W /35NENW

Location #: 310232



Photo #3

70 RanchUSX BB 35-03 Battery site

Abandoned

Unused Equipment

Gas meter run, riser, equipment



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources