

Hicks PA 444-6
Api. # 05-045-222406
Inspection # 689703051



Hicks PA 444-6
Api. # 05-045-222406
Inspection # 689703051



Weeds cleared around separators as per inspection
689702465

Hicks PA 444-6
Api. # 05-045-222406
Inspection # 689703051



Weeds cleared around tanks as per inspection 689702465

Hicks PA 444-6
Api. # 05-045-222406
Inspection # 689703051



Flow line from tanks to combustor disconnect and 1 support not connected the other 2 supports are leaning over.



Support not connected

Hicks PA 444-6
Api. # 05-045-222406
Inspection # 689703051



Supports leaning over.



Supports leaning over.

Hicks PA 444-6
Api. # 05-045-222406
Inspection # 689703051



Dead weed debris in ditch.



Dead weed debris in drain from wells to ditch.

Hicks PA 444-6
Api. # 05-045-222406
Inspection # 689703051



Dead weed debris covering north west of location.