

Inspection Photos
Operator: BP America
Location/API #: 067-07419
Date: 4-12-2019



Photo 1. View of the project area from the southwestern corner facing center.



Photo 2. View of the western project area from the southwestern corner facing northward.



Photo 3. View of kochia debris along the eastern edge of the working area.