

**PA 14-32**  
**Api. # 05-045-07416**  
**Inspection # 689703063**



**PA 14-32**  
**Api. # 05-045-07416**  
**Inspection # 689703063**



**Weed debris have been cleared.**



**PA 14-32**  
**Api. # 05-045-07416**  
**Inspection # 689703063**



**Rill between tank and separators.**



**Rill at fence of tank.**

**PA 14-32**  
**Api. # 05-045-07416**  
**Inspection # 689703063**



**Sediment moving in towards back of separators.**